Windows XP/2000 USB HDD Installation

Click **START | MY COMPUTER | MANAGE**

Click on **DISK MANAGEMENT**

You should see the above screen, in this case, our "Disk 1" is Unknown.

Click on the "Red dash icon" then click **Initialize Disk**

Click the window area then click on **New Partition**

Click **NEXT**

Select "Primary partition" then click **Next**

Choose the maximum Partition size then click **Next**

Assign a drive letter then click **Next**

Select the "FAT32" file system then click **Next**

Click **Finish**, your new drive is now available.